Mary A. Gade, Director

2200 Churchill Road, Springfield, IL 62794-9276

217/782-3362

July 12, 1995

Mr. Kenneth Braig Riedel Environmental Services, Inc. 18207 Edison Avenue Chesterfield, MO 63005-3703

Dear Mr. Braig:

Water quality criteria are enclosed for the several substances above detection level on your list. The criterion for 2-nitroaniline is estimated and could not be utilized directly to calculate effluent limits in a permit. If the effluent of your process did actually contain 2-nitroaniline at the level indicated in your analysis report, it is possible a bioassay might be required. However, once the Permit Section has reviewed your application for an NPDES permit, other factors may prevail. In particular, technology based limits for you treatment process would be applied.

CAS#		Acute	Chronic	<u>Human</u>	Unit
67-64-1	acetone	1. 5 3	0.122	•	g/l
120-63-2	2,4-dichlorophenol	0.631	0.083	-	mg/l
88-74-4	2-nitroaniline	[2]	[0.2]	-	mg/l
84-66-2	diethylphthalate	•	•	30	mg/l

Sincerely,

Clark S. Olson

Standards and Monitoring Support Unit

Planning Section

Division of Water Pollution Control

CSO:dle.braig



RIEDEL ENVIRONMENTAL SERVICES

a wholly owned subsidiery of Smith Environmental Technologies Corporation

SAUGET LANDFILL SITE G 1216 Queeny Ave. Sauget, IL 62206 618/332-6508(Phone) 618/332-6520(Fax) FAX COVER PAGE

To: Sea Borries	
From: Ken Brolg	
Date: 7-18-95	
Number of Pages Including Cover Page:	
REMARKS: Urgent	
MESSAGE: Soil suples from the southwart and southeest corners of the site canc back at appm, so additional will not be required on the corners I also recieved this letter from IEPA concurring discharge effluet limits.	